



Cobra Motorcycle Mfg.

240 Uran Street
Hillsdale MI, 49242


(517) 437 9100 phone
(517) 437-9101 fax

TSB0406: King Rear Shock

December 5, 2005

⚠ WARNING

Early King 2006 models have a rear shock with in improperly installed o-ring between the shock body and top piece. This can allow the unit to separate, causing loss of oil pressure, and improper operation. If the Fox shock on your 2006 King does not have the identification marks shown below you must send your shock to Fox for a replacement, free of charge.



Please contact Amanda Keel at Fox to arrange the shipping and exchange of your King shock at no charge to you.

Akeel@foxracingshox.com

(831) 274 8330 Pacific Standard Time