



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

(517) 437-9100 phone  
(517) 437-9101 fax

## TSB1208 CX65 Clutch pressure plate

March 6, 2008

If CX65 customers experience bending of the clutch pressure plate (ECDC0071) or have the clutch hydraulic system loose fluid (into the transmission), the short term fix is to install two ECDC0071 pressure plates. Shortly, Cobra will have available a thicker plate setup (ECMU0224).

