



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

(517) 437-9100 phone  
(517) 437-9101 fax

## TSB1512 Solenoid Care on 2012 CX65

April 25, 2012

In order to keep solenoid wires from breaking, care must be taken not to rotate the solenoid housing when loosening the power valve cap. The cap does not need to be installed very tightly, in fact if the sealing o'ring is lubricated, then hand tight will be sufficient.



To avoid solenoid rotation, it may be necessary to squeeze the solenoid body with a tool.



squeeze here if necessary



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

---

(517) 437-9100 phone  
(517) 437-9101 fax