



Technical Service Bulletin


Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB01711 Top Triple Clamps on King and CX65

There have been some rare occurrences of the top triple clamps developing a stress crack near the pinch bolts on both 2011 King and CX65. The picture below shows where to look.



Please contact Cobra Customer Service if you have had this occur.