



Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB01811 JR Ignition Coil

The mounting location of the ignition coil (IAMU0005) on the 2004 – 2011 CX50 JR / CM models makes the 105 458 circuit pack subject to high heat from the engine and pipe. Cobra is switching to a new PVL coil (ICCJ0001) on the JR model which moves the 105 458 circuit pack to a side of the coil away from the engine and pipe to keep it cool.

As the circuit pack is identical between the units there is no performance difference. The new coil will hold up better in long races under high heat conditions.

The ICCJ0001 will now be the standard coil on all Cobra CX50 JR models and is also the recommended service replacement coil for all 2004 – 2011 CX50 JR/ CM models.

