Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0813 Autolite Spark Plugs for 2007–2011 CX65

The Autolite XS62 (Cobra ECMU0015I) service replacement iridium plug has been replaced by Autolite XS61 (Cobra ECMU0010I).

This affects 2007 – 2011 CX65 and ECX70 engines.