Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0315

Intake Manifolds for King & JR with non V-Force Reeds

The intake boot (ECKG0203) for the 50 cc engines built prior to V Force reeds is no longer available. The replacement parts are:

- Manifold RCCS0002
- Gasket ZCMU0132

Install the gasket (ZCMU0132) and the manifold (RCCS0002) in place of the ECKG0203 manifold.

The impacted models are listed below.

Model	Year
King	2002- 2007
King	2009 - 2010
JR	2003 - 2007
JR	2009 - 2011
ECX50	2006 - 2010