Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran Street
Hillsdale MI, 49242

(517) 437 9100 phone
(517) 437-9101 fax

TSB0404: 2004 King potential pinched ignition wire location.

April 2, 2004

On some of the 2004 model King 50's it is possible that the ignition cut off switch (kill switch) wires, or the stator wires, can get pinched between the ignition coil frame and the gas tank (see picture).

Remove the fuel tank and closely inspect the wire for compromises in the insulation (bare wires, indentations, etc...) Cover any blemishes with electrical tape and reroute the wires such that a generous amount of clearance is insured.