Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0411 50cc Output Shaft

From 2006 through 2010 the output shaft on the King and JR/CM models has been ECMU0099. From this time forward, the service replacement part for these models will be the output gear ECMU0999 with a snap ring ECKGSR03 sold together as a Descriptor Kit DECMU0999.



This new gear and clip is the 2011 production hardware.