Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

January 11, 2017

Reed Pedal Service Intervals on 2017 CX65
TSB1417

Cobra recommends the reed pedals should be replaced every 10 hours of engine operation to avoid engine damage.

The upper reed pedals appear to be wearing prematurely and if left unattended will break off and get sucked into the engine.