Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

March 30, 2017

Chain Sliders for 2017 50's and 2016 FWE
TSB1717

To avoid the chance of the front sprocket catching the chain slider, improvements, as shown below, have been made effective March 31, 2017.

GCMU0040 and GCMU0033 ordered from March 31, 2017 and forward will have the modifications as shown below.

For owners of 2017 CX50 P3/JR/King/FWE or 2016 CX50 FWE, we advise that you remove your chain slider and trim per the picture below.