Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0209 Reeds for 2008 King

September 17, 2008

The reed assembly (ECCS0005), intake Manifold (RCCS0002), and gasket (ZCCS0001) for the 2008 King have been replaced with the similar parts used on previous model Kings and CM/JR models. The part numbers for the replacement parts are:

Reed Assembly	ECKG0202
Intake Manifold	ECKG0203
Gasket	ZCMU0132