Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0409 Cobra JR / OI Radiator with Louvers

October 15, 2008

The 2009 model year radiator for Cobra JR (also remaining OI) model will be FCCJ0004 which now has provisions for louvers. On the 2009 models these louvers also rely on a feature on the frame down-tube for mounting the plastic louvers. Older models do not have these features on the frame and so it is not possible to utilize the louver mounts on the radiator.

Customers with older models JR/CM or OI/P3/PW3 needing a replacement radiator for ECMU0061 or ECMU0225 will be sold a radiator kit FKMU0001 which includes the new style radiator, FCCJ0004C (with louver mounting tabs removed), and all mounting hardware. This will allow the mounting of the new style radiator onto these products without mounting the louvers.

As the 2009 frame is now the service replacement frame for JR/CM & OI/PW3/P3 models from 2004 – 2008, the louvers are able to mount on all older models JR/CM & OI/PW3/P3 that have the appropriate mounting provisions.

⚠ WARNING

Welding on the highly stressed down-tube frame member is not recommended by Cobra because it can cause premature structural failure to the frame and possible injury to the rider.