Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

November 20 2014

TSB0615
2013- 2014 CX65 Power Valve and Solenoid

Going forward, the 2015 PV assembly will be the recommended service replacement components for customers needing replacement components for 2013 - 2014 Power Valve assemblies. The required component assemblies are shown below

Item	Description	Part Number
1	Valve Assembly	EAC60016
2	Solenoid Assembly	EAC60015