Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB1107: CX65 Top End

May 21, 2007

The cylinder on the Cobra 2007 CX65 was supplied to Cobra, from the manufacturer, with incorrect specifications. Cobra can best take care of its many customers through factory controlled changes to the cylinder and a correspondingly different cylinder head.

An updated cylinder can be recognized by having a “U” stamped in near the exhaust as shown below. The cylinder head can be recognized by having a ‘dimple’ on the water-jacket surface shown.



All units produced of Revision 1.5 and higher will have this upgraded hardware direct from Cobra. Customers with units produced prior to Rev 1.5 may call into Cobra and arrange an upgrade of cylinder and head. This will require the customer to receive a proper Return Authorization number (RA#) prior to sending in their cylinder and head.

Call 517 437 9100 x115 to make arrangements with a Cobra customer service representative. Please have serial number and name of dealer available when speaking with the representative. Customers will be responsible for shipping parts to Cobra and Cobra will cover ground shipping back to the customer.

Ryan Holliday will have representative samples of cylinder and head for verification purposes.