Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB1508 Ø47.6mm Piston Ring Life

May 20, 2008

As the Ø47.6mm piston has only a single ring, it will receive increased wear. Also, because there is only a single ring, the importance of it sealing properly is important to compression.

It is recommended to change this piston ring between 1 hour and 1 ½ hour of operation.