Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

November 17, 2015

TSB0516
Sprocket Shims

For 2016 CX50 models may have shims behind the countershaft sprocket that tighten up the fit. These shims are available in three different thicknesses to account for wear and different sprocket thicknesses.