Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

April 2, 2016

TSB01016
CX65 Kick Ramp and Ramp Gear
For 2014 and Older Models

Kick ramp gear ECC60145 used in kick mechanism EADC0003 (2007 CX65 – 2014 CX65) is no longer available. Customers needing this gear will need to get ramp gear ECC60201 which is used in mechanism EAC60020.

Customers making this change will also need to replace their older kick ramp (ECC60144) with the newer style ECC60200. The newer style will also require that the customer purchase flat head screw HCFH0616 for proper installation.