Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

March 30, 2017

Clutch Bolts for CX50 Clutch Stacks
TSB1817

Due to a supply chain interruption, Cobra is out of stock of the HCBT0001 clutch bolts. During this time, Cobra will be producing motorcycles, and selling clutch assembles, with the previous style of clutch bolt (HCBS0004).

Cobra will revert to shipping our latest style bolt and stack as soon as possible. This will be announced through our dealers, through the news section of our website, **www.cobramoto.com** , and through social media channels.