Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

July 18, 2018

TSB0119
CX50 Front Fenders

To work with the new forged triple clamps for 2019 the front fenders have changed the bolt pattern. It is NOT the same as the old JR bolt pattern.

		JR / P3	King	Factory Works
2010 – 2018	Front Fender	TCHA0107	TCMU0016	TCMU0016
	Bodywork Kit	TKCJ0002	TKCS0001	TKFW2018
2019	Front Fender	TCMU0034	TCMU0034	TCMU0034
	Bodywork Kit	TKCJ2019	TKCS2019	TKFW2019