Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

September 26, 2017

CX50 Torque Specification Correction

Some manuals may have incorrect torque values listed for certain fasteners. Below are listed the correct values.

FW / King / JR / P3

Fastener	Torque Value			Loctite™	Size & Remarks
	ft-lb	in-lb	Nm		
Water pump impeller	3	36	4	263	M5 x 0.8
Front axle aluminum bolt	18	221	25	243	M10 X 1.25