Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

March 1, 2018

TSB1118
Radiator Mounting CX65 2017 - 2018

Issue:
Some customers are having issues with radiators leaking prematurely on 2017 – 2018 CX65.

Action:
Mounting the radiator less rigidly and taking strain off the bottom hose spigot with a kit of parts, FKC60002. Parts included in the kit are;

Parts included in FKC60002		
Part Number	Description	Quantity
FCC60060	RADIATOR CX65 2012-CURRENT	1
TCC60222FLL	SHROUD LEFT - FLO YELLOW CX65 - FLEX	1
MCMUGR03	GROMMET – EXTRA WIDE	2
TCC60017	WASHER - 5MM BODY PANEL	1
ECC60192M	HOSE - LOWER RADIATOR	1
FCC60074	SPACER – EXTENSION for FRAME MOUNT	2