Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

July 7, 2022

TSB1222
Rear Brake Master

Due to supply issues, Cobra motorcycle's may have one of two different rear brake master cylinders. Each has a different rebuild kit.

Rebuild kit
BCKG0015 (11.0mm)

Rebuild kit
BKC60009 (12.9mm)



Rebuild kit
BKMU0011 (11.0mm)