Technical Service Bulletin

Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242
(517) 437-9100 phone
(517) 437-9101 fax

July 30, 2024

TSB0425 CX65 swingarm update 1

Customers with CX65 2022 – 2024 needing a replacement swingarm will need GAC62025.

Keep in mind that this assembly does NOT come with chain adjust bolts, or chain guide and guard. Those parts are sold separately. List below:

Description	Cobra #
Front chain guard	PCC60006
Chain guard fasteners	HCFH0516 (2 REQ'D)
Bottom chain guard	PCC60004
Chain guide bolt	HCBC0645 (2 REQ'D)
nut	HCNF0602 (2 REQ'D)
Brake line clamp	GCC60051
Brake line clamp fasteners	HCFH0516 (2 REQ'D)
Chain adjust bolt	HCBH0701 (2 REQ'D)
Chain adjust jam nut	HCNS0701 (2 REQ'D)

UPDATE: original document had the GCC60051 part number mistakenly shown as HCC60051