



Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0212 Autolite Spark Plugs

The Champion 8339 spark plug is being phased out of use as a production or service replacement unit.

The future spark plug for Cobra products will be a combination of copper core plugs in production and an iridium fine wire plug for service replacement.

	Production (Copper Core)	Service Replacement (Fine Wire Iridium)
JR	ECMU0010C	ECMU0010I
King	ECMU0010C	ECMU0010I
CX65	ECMU0015C	ECMU0015I
ECX50 engine	ECMU0010C	ECMU0010I
ECX70/80/88	ECMU0015C	ECMU0015I

Cobra #	Autolite #
ECMU0010C	4261
ECMU0010I	XS61
ECMU0015C	4262
ECMU0015I	XS62