



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

(517) 437-9100 phone  
(517) 437-9101 fax

## TSB0412C 50cc Cylinder Kits for Service Replacement

From this time forward Cobra will only be offering the ECCJ0001 cylinder kit, with o'ring groove in cylinder for concentric head locating, as the standard service replacement part for engines previously using the ECMU0129 cylinder kit.

The customer will need to purchase the corresponding cylinder head insert (ECCS0017) that goes along with this cylinder, and four 7mm studs with 6mm threads.

The affected models include

Model	Years
SR (King)	1998 - 2010
JR	2001 - 2011

This will require the user to also replace the 6mm cylinder studs, washers and nuts, with 7mm hardware. Part numbers for 7mm hardware that works with older cases is listed below. This paragraph and table were added March 1 2012.

Description	Part Number
7mm Stud with 6mm End	ECMU0147B
Nuts	HCNS0702 or HCNS0703
Washers	HCWF0701 or HCWS1401

The above parts are available in kit EKMU0013.