



Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB0110 Steering Stem Cap CX65

It is possible for water and dirt to accumulate in the steering stem of the Cobra CX65 after riding and washing. This mixture of dirt and water then can be siphoned into the vent tube or plug it off if the vent tube has sufficient length into the steering stem.

To avoid the accumulation of water and dirt into the steering stem, Cobra has introduced into production and has available a steering stem cap (FCMU0151) fits securely over the top of the steering stem jam nuts and has a hole to hold the vent tube.

This cap will also improve the useful life of the steering stem bearings.

