



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran street  
Hillsdale, MI 49242

(517) 437-9100 phone  
(517) 437-9101 fax

## TSB0215 King and CX65 Shroud Screws

The radiator shrouds on the 2015 King and CX65 have been installed with self tapping screws that will strip the plastic threads out of the tank if tightened to a torque value greater than that required to keep the shroud from vibrating.

The proper torque value is a Maximum of 12 in-lb (1 ft -lb or 1.3 Nm).

This is about the same amount of torque one would use to tighten the screws on a light switch cover in your home.

Without having an 'inch-lb torque wrench' the best method of assembly is to turn the fastener in until resistance is felt. Confirm that the shroud will not wiggle. If it does, tighten just enough more so that the shroud is secured.