




Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242


(517) 437-9100 phone
(517) 437-9101 fax

TSB0311 Kick Lever for older models

Cobra King and JR models 2010 and older use the ECDC0046 clamp style kick lever.



This kick lever assembly is no longer available for service replacement as the clamp style 'pivot' is now obsolete. We do still offer the following replacement parts to help service older units.






Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

If a complete kick lever assembly is required, customers will be required to purchase a new style kick shaft/gear along with new style kick lever assembly.



If the threads strip out of the ECDC0046 swivel, a longer bolt with a nut may be an option, or likewise a heli-coil, may be a cost effective alternative to purchasing a new kick lever and gear.