



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

240 Uran Street  
Hillsdale MI, 49242

(517) 437 9100 phone  
(517) 437-9101 fax

## TSB0904: 2004 King performance tuning

April 2, 2004

Time has shown that the 2004 King should be jetted with larger main and pilot jets than Cobra owners have been used to. Also, ignition timing may be retarded from stock values to increase top end 'over-rev'.

	Stock	Optimal
Main Jet	94	95
Pilot Jet	60	65
Ignition Timing	0.045" (1.14mm) BTDC	0.030" – 0.045" (0.76 – 1.14mm) BTDC