



# Technical Service Bulletin

**Cobra Moto, LLC**

240 Uran Street  
Hillsdale, Michigan 49242

(517) 437-9100 phone  
(517) 437-9101 fax

November 17, 2015

## TSB0516 Sprocket Shims

For 2016 CX50 models may have shims behind the countershaft sprocket that tighten up the fit. These shims are available in three different thicknesses to account for wear and different sprocket thicknesses.

