

## **Technical Service Bulletin**

Cobra Moto, LLC

240 Uran Street Hillsdale, Michigan 49242 (517) 437-9100 phone (517) 437-9101 fax

July 18, 2018

## TSB0119 CX50 Front Fenders

To work with the new forged triple clamps for 2019 the front fenders have changed the bolt pattern. It is NOT the same as the old JR bolt pattern.

|                |                 | JR / P3  | King     | Factory<br>Works |
|----------------|-----------------|----------|----------|------------------|
| 2010 –<br>2018 | Front<br>Fender | TCHA0107 | TCMU0016 | TCMU0016         |
|                | Bodywork<br>Kit | TKCJ0002 | TKCS0001 | TKFW2018         |
| 2019           | Front<br>Fender | TCMU0034 | TCMU0034 | TCMU0034         |
|                | Bodywork<br>Kit | TKCJ2019 | TKCS2019 | TKFW2019         |