

Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street Hillsdale, Michigan 49242 (517) 437-9100 phone (517) 437-9101 fax

December 21, 2017

Customer Service Chains for CX50's

The current customer service 100 link 420 heavy duty chain for Cobra 50's (PCMU0100) is being replaced by 102 link (PCMU0102) so that it will also work for the CX50FWE with the longer swingarm.

Customers installing this chain onto a King will need to cut the length to 100 links.

Customers installing this chain onto a JR or P3 will need to cut the length to 88 links.