

Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street Hillsdale, MI 49242 (517) 437-9100 phone (517) 437-9101 fax

TSB0414 CX65 CDI unit

December 20, 2013

The 2014 CDI unit for the Power Valve CX65 has improved ignition values that reduce or eliminate the high RPM 'popping' some have experienced in 2013. From this time forward the new 2014 box will be considered the standard service replacement for all CX65 power valve bikes from 2012 on.

The 2014 CDI box can be identified by the date code. It will have a date code of "1013" (October 2013) or later as identified in the picture below.

