



Technical Service Bulletin


Cobra Moto, LLC
240 Uran Street
Hillsdale, Michigan 49242

(517) 437-9100 phone
(517) 437-9101 fax


July 7, 2022 Updated 3/4/24

TSB0324 (update 2 of TSB1222) Rear Brake Master Rebuild Kits

Due to supply issues, Cobra motorcycles may have one of three different rear brake master cylinders. Each has a different rebuild kit.



Formula - Rebuild kit
BCKG0015 (11.0mm)



Import Rebuild kit
BKC60009 (12.9mm)



CARD import -Rebuild kit
BKMU0011 (11.0mm)



CARD made here

Kg/FW/65/JR

BKMU0014 - 2024 and later with captured clevis

BKMU0011- 2023 and older without captured clevis