



## Technical Service Bulletin

Cobra Moto, LLC

240 Uran Street  
Hillsdale, Michigan 49242

(517) 437-9100 phone  
(517) 437-9101 fax

April 28, 2025

### TSB1125 Replacement Power Valve

Cobra can no longer make the valve assembly for 2015 / 2016 power valve (EAC60016). If a customer is needing one, they must get the valve assembly and solenoid assembly for 2017. Some grinding to the frame may be necessary.

This includes an update to TSB0721 regarding 2013 – 2014 valve hardware

	2013-2014	2015 - 2016	2017
Valve or Assembly	ECC60150 ECC60164 EKC60004	EAC60016	EAC60035
Solenoid Assembly	ECC60100	EAC60015 (still in stock)	EAC60021