Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB1507: CX65 Airbox Water Protection

May 31, 2007

The Airbox on the CX65 has a relatively large area in the bottom for water to drain. In wet and muddy conditions, it is recommended that customers with this style of airboxe use “duct tape” or suitable product to seal the majority of the length of the slot in order to keep water out while still allowing some passage for water to escape if it should happen to get in.