



Technical Service Bulletin

Cobra Motorcycle Mfg.

240 Uran street
Hillsdale, MI 49242

(517) 437-9100 phone
(517) 437-9101 fax

TSB01311 CX65 Piston Life

The pistons in Cobra 2010 and 2011 CX65 should be inspected every 10 hours of service until further notice.

Look specifically for signs of cracking at the base of the skirts.