

## **Technical Service Bulletin**

Cobra Motorcycle Mfg.

240 Uran street Hillsdale, MI 49242 (517) 437-9100 phone (517) 437-9101 fax

## TSB0611 2010 CX65 Cylinder and Head Insert

On the 2010 CX65 it is possible for the 'self piloting 'cylinder and cylinder head to be off center (non-concentric) enough for the piston to contact the head insert. Cobra has come up with a solution for this which requires a new cylinder head insert and machining to the customer's cylinder. Cobra will perform this machining for \$25 if the cylinder is sent to the factory. New style cylinder head inserts are available.

## Part numbers

	New	Old
Head Insert	ECC60073	ECC60036
O'Ring	ZCMUOR05	ZCMUV032
Cylinder Kit	ECC60075	ECC60037

